



# INSPECTION REPORT



TO: <i>JENNIFER XU</i>		COMPANY: <i>Brown Daniels</i>	CONTACT INFORMATION (MAIL, EMAIL/FAX):
<i>SEAN THIBEAULT</i>		<i>YORK UNIVERSITY</i>	
<i>PETER BENSLEY</i>		<i>HIGH POINT</i>	
PROJECT: <i>WINTERS COLLEGE - YORK UNIVERSITY</i>		PINCHIN FILE NUMBER: <i>40323</i>	
PROJECT ADDRESS:		NUMBER OF WORKERS: <i>1</i>	
INSPECTOR: <i>D. Newton</i>	TIME IN: <i>4:30</i>	TIME OUT: <i>8:15</i>	

WORK AREA / WORK IN PROGRESS: *PINCHIN IS ON SITE TO COMPLETE AIR CLEARANCE TESTING OF THE TYPE 3 ENCLOSURE LOCATED IN THE BASEMENT.*

*- THE 3 PUM AIR SAMPLE RESULTS INDICATE THAT THE AVERAGE FIBRE LEVELS INSIDE THE ENCLOSURE ARE 0.01 f/ml AND ∴ WITHIN ACCEPTABLE LIMITATION ACCORDING TO O. REG. 278/05.*

*- CONTRACTOR MAY DISMANTLE ENCLOSURE FOLLOWING PROPER PROCEDURES.*

CASSETTE / SAMPLE NO.	PUMP NO.	START TIME	DURATION (Minutes)	FLOW RATE (L/min)	SAMPLE VOLUME (Litres)	DESCRIPTION OF SAMPLE	RESULT
<i>145734</i>	<i>994</i>	<i>4:45</i>	<i>160</i>	<i>15</i>	<i>2400</i>	<i>CLR - SOUTH BASEMENT AREA</i>	<i>0.01</i>
<i>145726</i>	<i>995</i>	<i>4:45</i>	<i>160</i>	<i>15</i>	<i>2400</i>	<i>CLR - " "</i>	<i>0.01</i>
<i>145716</i>	<i>12</i>	<i>4:45</i>	<i>160</i>	<i>15</i>	<i>2400</i>	<i>CLR - " "</i>	<i>0.01</i>

SIGNED: <i>[Signature]</i>	DATE (YEAR / MONTH / DAY): <i>07-04-10</i>	REPORT NUMBER: <i>3</i>	PAGE: <i>1</i> OF <i>1</i>
----------------------------	--	-------------------------	----------------------------