



INSPECTION REPORT



TO: <i>JENNIFER XU</i>	COMPANY: <i>BROWN DANIELS</i>	CONTACT INFORMATION (MAIL/EMAIL/FAX):
<i>SEAN THIBEAULT</i>	<i>YORK UNIVERSITY</i>	
<i>PETER BENILEY</i>	<i>HOVA PAPER</i>	

PROJECT: <i>WINTERS COLLEGE - YORK UNIVERSITY</i>	PINCHIN FILE NUMBER: <i>41323</i>
PROJECT ADDRESS:	NUMBER OF WORKERS: <i>3</i>

INSPECTOR: <i>D. NEWTON</i>	TIME IN: <i>9:15</i>	TIME OUT: <i>11:45</i>
--------------------------------	-------------------------	---------------------------

WORK AREA / WORK IN PROGRESS: *PINCHIN ENVIRONMENTAL IS ONSITE TO COMPLETE A FINAL VISUAL INSPECTION OF THE TYPE 3 REMOVAL OF ASBESTOS FITTINGS FROM THE SOUTH BASEMENT AREA - WINTERS COLLEGE*

- CONTRACTOR HAS REMOVED ALL NECESSARY ASBESTOS - FITTINGS

CASSETTE / SAMPLE NO.	PUMP NO.	START TIME	DURATION (Minutes)	FLOW RATE (L/min)	SAMPLE VOLUME (Litres)	DESCRIPTION OF SAMPLE	RESULT
<i>(Table is crossed out with a diagonal line)</i>							

SIGNED: <i>D. Newton</i>	DATE (YEAR / MONTH / DAY): <i>07-04-09</i>	REPORT NUMBER: <i>2</i>	PAGE: <i>1</i> OF <i>2</i>
-----------------------------	---	----------------------------	-------------------------------

